




INSTALLED VIEW




TOP VIEW



BOTTOM VIEW




FRONT VIEW [From foundation vent]



REAR VIEW [From crawl space]


FRONT & REAR VIEWS



SIDE VIEWS

# Moisture Scrubber

200 Gatewood Circle  
Athens, Georgia 30607  
706.548.2155



VENT the CRAWL